HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Pepco Power Substation (Convention Center Site, District of Columbia) 922 I Street, NW. Washington, D.C. HABS No. DC-388

Documentation:

3 exterior photos (1979) 11 interior photos (1979) 3 data pages (1980)

R. S. Scurlock, Photographer 1979

DC-388-1 NORTH (FRONT) ELEVATION

DC-388-2 NORTH (FRONT) AND EAST (SIDE) ELEVATIONS

DC-388-3 DETAIL, BAS-RELIEF ABOVE SECOND FLOOR

DC-388-4 BASEMENT, RIVETED CONSTURCTION FRAMEWORK

DC-388-5 BASEMENT, RIVETED CONSTRUCTION FRAMEWORK, CLOSE-UP

DC-388-6 BASEMENT, CONVENTIONAL STATION SERVICE

DC-388-7 FIRST FLOOR, SWITCHBOARDS, VIEW OF REAR DOOR

DC-388-8 FIRST FLOOR, SWITCHBOARDS, VIEW OF FRONT DOOR

DC-388-9 FIRST FLOOR, CAPACATOR BANK AREA

DC-388-10 SECOND FLOOR, SWITCH GEAR ALLEY

DC-388-11 SECOND FLOOR, SWITCH GEAR ALLEY

DC-388-12 DISCONNECTED PUMP MOTOR

DC-388-13 SPRING LOADED REGULATOR

DC-388-14 IMCOMMING WATER, FIRE PROTECTION VALVE